ZP3 USB Programmer Software Installation

Read this document before connecting the ZP3 USB Programmer to your computer.

Software Installation:


1.Run Setup.exe on the CD, and follow the prompts.

USB Driver Files:

2.1 Connect the USB programmer to the PC, using the supplied mini-USB cable.




2.2 Select No, and click Next



2.3 Select "Install from a list or specific location" and click Next



2.4 Select "Don't search, I will choose the driver to install", and click Next



2.5 Select Universal Serial Bus Controllers, and click Next



Select "Have Disk" and click Next




2.6 Browse to Program Files\GE Security\ZP3 USB Programmer\USB Drivers\, and click OK




2.7 Click Next



2.8 Click Continue Anyway.



2.6 Wait while drivers install



Click Finish when done.